Results of Checking the Status of Use of PFOS

V1.0 2007/9/1

【Information on Surveyed Company (Supplier)】

Company code:	ASEE
Company name/site or plant name:	ASE Electronics INC.
Location:	73. Kai Fa Rd., Nantze Export Processing Zone, Kaohsiung Taiwan 811,
Department/division name:	QA
Completed by:	Byron Wang
E-mail:	Byron Wang@aseglobal.com
Phone:	(07)3658500#73241
Fax:	(07)3658460
Date of completion:	2007-10-31

《Comments Field》 * Please write your comments, requests, or messages here (optional).

	Write the part number you supply to ASAT.	Write the name of parts or products you supply to ASAT.	Specify the location where PFOS is used and its application.	Specify whether or not an alternative technique is available.	Outline the alternative technique, for example, an alternative material.	Write issues related to replacement, if any.	Specify the timing of switchover to replacement.	Write suggestions or notes (optional).
No.	**ASAT's part number**	**Product name**	**Location where PFOS is used/purpose**	**Availability of alternative technique**	**Outline of alternative technique**	**Issues related to replacement**	**Timing of switchover**	**Remarks**
Sample 1	AXXX-XXXX	PC board	Penetrant and wetting agents	None	—	—	To be determined	
Sample 2	BXXX-XXXX	Sliding bearing	Slide materials	Available	Switchover to alternative material	Performance degradation	January 1,2008	
1	01096006-1	Substrate	N/A	-	-	-	-	
2	01324016-1-A51	Substrate	N/A	-	-	-	-	
3	E01400005-1-A51	Substrate	N/A	-	-	-	-	
4	01256085-1-A51	Substrate	N/A	-	-	-	-	
5	E01329005-2-A51	Substrate	N/A	-	-	-	-	
6								
7								
8								
9								
10								
11								
12								