



Test Report

DYNACRAFT INDUSTRIES SDN BHD
255-A, BLOCK D, PHASE 2, BAYAN LEPAS INDUSTRIAL ZONE, 11900
PENANG, MALAYSIA.


Report No. : KA/2008/70205
Date : 2008/07/07
Page : 1 of 4



The following sample(s) was/were submitted and identified by/on behalf of the client as :

Sample Description : ADVANCED MICRO NiPdAu LEAD FRAME USING RAW ALLOY BLANK A42
Stock No. : SN157339SAXA
Job No. : 350356
Manufacturing Date : 22nd JUNE 2008
CTS Reference No. : CTS/08/3157/DYNACRAFT
Sample Receiving Date : 2008/07/02
Testing Period : 2008/07/02 TO 2008/7/7

Test Result(s) : - Please see the next page(s) -


Katherine Ho / Supervisor
Signed for and on behalf of
SGS Taiwan Limited

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明，此報告結果僅對測試之樣品負責。本報告未經本公司書面許可，不可部份複製。

This Test Report is issued by the Company under its General Conditions of Service printed overleaf or available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this Test Report is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Test Report

DYNACRAFT INDUSTRIES SDN BHD

255-A, BLOCK D, PHASE 2, BAYAN LEPAS INDUSTRIAL ZONE, 11900 PENANG, MALAYSIA.

Report No. : KA/2008/70205

Date : 2008/07/07

Page : 2 of 4



Test Result(s)

PART NAME NO.1 : SILVER METAL

Test Item (s)	Unit	Method	MDL	Result
				No. 1
Halogen	---	---	---	---
Halogen-Chlorine (Cl) (CAS No.: 022537-15-1)	mg/kg	With reference to BS EN 14582 . Analysis was performed by IC method for Chlorine content.	50	n.d.
Halogen-Fluorine (F) (CAS No.: 014762-94-8)	mg/kg	With reference to BS EN 14582 . Analysis was performed by IC method for Fluorine content.	50	n.d.
Halogen-Bromine (Br) (CAS No.: 010097-32-2)	mg/kg	With reference to BS EN 14582 .Analysis was performed by IC method for Bromine content.	50	n.d.
Halogen-Iodine (I) (CAS No.: 014362-44-8)	mg/kg	With reference to BS EN 14582 . Analysis was performed by IC method for Iodine content.	50	n.d.

- Note :
1. mg/kg = ppm
 2. n.d. = Not Detected
 3. MDL = Method Detection Limit
 4. " --- " = Not Conducted

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明，此報告結果僅對測試之樣品負責。本報告未經本公司書面許可，不可部份複製。

This Test Report is issued by the Company under its General Conditions of Service printed overleaf or available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this Test Report is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Test Report


DYNACRAFT INDUSTRIES SDN BHD
 255-A, BLOCK D, PHASE 2, BAYAN LEPAS INDUSTRIAL ZONE, 11900 PENANG,
 MALAYSIA.

Report No. : KA/2008/70205
 Date : 2008/07/07
 Page : 3 of 4



Analytical flow chart of halogen content

- 1) Name of the person who made measurement: Hungming Li
- 2) Name of the person in charge of measurement: Ray Chang



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明，此報告結果僅對測試之樣品負責。本報告未經本公司書面許可，不可部份複製。

This Test Report is issued by the Company under its General Conditions of Service printed overleaf or available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this Test Report is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Test Report

DYNACRAFT INDUSTRIES SDN BHD
255-A, BLOCK D, PHASE 2, BAYAN LEPAS INDUSTRIAL ZONE, 11900
PENANG, MALAYSIA.

Report No. : KA/2008/70205
Date : 2008/07/07
Page : 4 of 4



** End of Report **

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明，此報告結果僅對測試之樣品負責。本報告未經本公司書面許可，不可部份複製。

This Test Report is issued by the Company under its General Conditions of Service printed overleaf or available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this Test Report is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.