

Results of Checking the Status of Use of PFOS

V1.0 2007/9/1

Information on Surveyed Company (Supplier)

Company code:	(Common/local)
Company name/site or plant name:	Sumitomo Bakelite Singapore Pte Ltd
Location:	Singapore
Department/division name:	Quality Assurance
Completed by:	Gemi Tan
E-mail:	gemitan@sbs.sumibe.co.jp
Phone:	
Fax:	
Date of completion:	1st Nov 2007

Comments Field)* Please write your comments, requests, or messages here (optional).

No.	Ricoh's part number	Product name	Location where PFOS is used/purpose	Availability of alternative technique	Outline of alternative technique	Issues related to replacement	Timing of switchover	Remarks
Sample 1	AXXX-XXXX	PC board	Penetrant and wetting agents	None	-	-	To be determined	
Sample 2	BXXX-XXXX	Sliding bearing	Slide materials	Available	Switchover to alternative material	Performance degradation	January 1,2008	
1		EME-6300 Type HJ	Not intentionally formulated					
2		EME-7320C Type R	Not intentionally formulated					
3		EME-6710 Type SJ	Not intentionally formulated					
4		EME-6650R Type A	Not intentionally formulated					
5		EME-7372 Type	Not intentionally formulated					
6		EME-G770 Type C	Not intentionally formulated					
7		EME-G700 Type	Not intentionally formulated					
8		EME-7351Type LS	Not intentionally formulated					
9		EME-G760Q Type	Not intentionally formulated					
10		CRM-1079B	Not intentionally formulated					
11		CRM 1146A	Not intentionally formulated					
12		CRM 1146B	Not intentionally formulated					
13		CRM 1580A	Not intentionally formulated					
14		CRM 1525D	Not intentionally formulated					
15		CRM 1575CS	Not intentionally formulated					
16		CRM-1076NS	Not intentionally formulated					
17		CRM-1076W	Not intentionally formulated					
18		CRM-1076WA	Not intentionally formulated					